


N60201.AR.000510  
NS MAYPORT  
5090.3a

LETTER REGARDING FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
REVIEW OF WORK PLAN ADDENDUM 4 FLEET TRAINING CENTER DETENTION POND  
DEMOLITION AND REPLACEMENT NS MAYPORT FL  
5/5/2000  
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION



# Department of Environmental Protection

Jeb Bush  
Governor

Twin Towers Building  
2600 Blair Stone Road  
Tallahassee, Florida 32399-2400

David B. Struhs  
Secretary

May 5, 2000

Ms. Adrienne Wilson  
Department of the Navy, Southern Division  
Naval Facilities Engineering Command  
2155 Eagle Drive, PO Box 190010  
North Charleston, SC 29419-9010

file: 14pond\_add4a.doc

RE: Work Plan Addendum No. 4, Fleet Training Center Detention Pond Demolition and Replacement. Bechtel Environmental Incorporated. U.S. Naval Station, Mayport, Florida

Dear Ms. Wilson:

I have reviewed the above document dated April 2000 (received April 28, 2000). The Navy should be aware that after the soil is stockpiled during construction, TCLP analysis might indicate that a situation governed by RCRA could exist (for example, the analysis may indicate that one or more contaminants exceed TCLP levels in the stockpile). Other than to note that high density polyethylene liner material is measured in mils (1 mil. = 0.001 inch, page 1-5), the report is acceptable for its intent. If you need further clarification or any additional information, please feel free to contact me at 850-921-4230.

Sincerely,

James H. Cason, P.G.  
Remedial Project Manager

CC: Randy Bishop, NAVSTA Mayport  
Charlie Radford, CH2M Hill, Atlanta

TJB B JJC JJC ESN ESN